



I love Geometric Design and Tolerancing. It's such a beautiful metanoia above linear dimensioning schemes. It thinks about things in a fundamentally different way.

But most people hate it. And so most people want to use it like linear dimensioning schemes: just another way to prescribe dimensions that the boss-man says we need to do. But GD&T does not answer the same question that linear dimensioning does - or at least, it answers questions higher than linear dimensioning does. Take for example these two drawings of the same parts meant to fit together. On the left, the part is drawn linearly. On the right, with GD&T callouts.

The left is pretty easy to understand at first sight. But once we get into tolerancing - it becomes rigid and tyrranical, and even though it is verbose, it is ultimately less helpful in determining how accurate one must be. The advent of computerized machining further reduces the need for this verbosity.

Many designers make drawings out of necessity to get parts made - but forget what they are doing, and why they are doing it. They ask questions about "how precise does this need to be?", without asking the more important questions such as: "In what way does this need to be precise? What does this need to be precise relative to?"





A drawing in this fashion, using GD&T, not only increases readability, but conveys a very different message. This drawing better conveys the relationship between parts. It is useful to make the part, and readily tied back and checked by the part's function in the larger system.

The holes are called out as a pattern - already, they have a relationship to themselves, and are dimensioned accordingly (with a 0.02 tolerance zone). These holes are then deemed to be datum A.

The top surface (from J to K) is dimensioned not with particularities, but as a zone. This zone is 0.1 in width, and is not with respect to some arbitrary surface, but with respect to the mounting holes (datum A). Now it is clear to see what sort of precision is required to make this surface – and that precision is in relationship to something that matters.